Title:Barix_Logo_Claim_Pos.eps Creator:Adobe Illustrator(R) 15.1 CreationDate:19.09.12

Release Note

SIP CLIENT V2.16

Document Name:	Release Note		
Document ID:	20160720ASI1		
Document Date:	20. Jul. 2016		
Document Version:	V1.00		
Firmware name:	SIP CLIENT V2.16		
FW Release Date:	20. Jul. 2016		
Package Name:	abcl_sip_v2.16_20160720.zip		
Version Overview:	Type Firmware WEB UI FW Ext. 1 FW Ext. 2 FW Ext. 3 Bootloader	File name abclw.rom abclapp.cob sg.bin fs.bin bclio.bin exfull.rom	Version Date VB1.18_20160720 V02.07_20140820 V10.15_20160707 V02.08_20140820 V02.06_20151028 V99.28_20160624

1 Hardware Compatibility

This firmware is fully supported on the following devices:

- Annuncicom PS1, PS16,60,100,155,200,1000
- Extreamer 100,105,110,120,200,205,P5 as receivers only
- Instreamer as encoder only

The firmware is partially supported on the following modules:

- IPAM 100/102
- IPAM Carrier Board
- IPAM 300/302

Note: The firmware can run on any other Barix audio devices (e.g. Exstreamer Digital), however the functionality is not guaranteed

2 Fixed Bugs

The following bugs have been fixed compared to the previously released V2.14:

- Fixed the opaque parameter in the authentication response to be sent only if requested by the server
- Bug HY-135: Solved audio noise at startup

3 New Features and Improvements

The following new features have been fixed compared to the previously released V2.14:

- Added support for authentication using the Quality of Protection (qop="auth")
- Fixed to detect properly the SIP headers from the SipXecs server
- New feature HY-136: Added backup SIP server

4 Known Issues

- When a X8 contact that is configured as input is tried to be set using DTMF command 3, the active call will be closed as it will be detected as a button press. Calculate properly the bitmask used in this command so that it does not try to set to "1" X8 pins configured as inputs. This issue is valid also for all versions of SIP client prior to V2.01;
- 2. In order the status of X8 contacts to be correctly displayed after using DTMF command 4, the SIP client needs to be rebooted in order the X8 device to be properly reinitialised with the new settings.
- 3. The inputs supervision is fully supported only on Annuncicom 155. When run on Annuncicom 1000, the inputs are shown as normal 2 state (open/close) inputs.

4. Decoding DTMF commands does not work properly when the remote peer is sending them both as DTMF digits and via the SIP INFO message. In this case configure the remote peer to use only one of these methods.

5 Release generating details¹

5.1 GIT release tag

Checkout the barix and bcl GIT repositories with the following tag:

abcl_sip_v2.16_20160720

5.2 Compile commands:

Run the following command from the cloned barix folder:

make ab_sip

5.3 Regenerating the FW image

The source code of the SIP Client application is too big in size, and cannot fit into the COB file together with the tokenized BCL code. The generated release already has the source code stripped out of the FW image. However, if for some reason manual rebuild of the FW is needed, then the *applications.sh* script or the *applictns.bat* batch file has to be run with the *-no_source* option to regenerate the applications.cob file:

./applications.sh -no source

¹ This information is intended for BARIX developers only

6 Legal Information

© 2016 Barix AG, Zurich, Switzerland.

All rights reserved.

All information is subject to change without notice.

All mentioned trademarks belong to their respective owners and are used for reference only.

Barix and SIP CLIENT are trademarks of Barix AG, Switzerland and are registered in certain countries.

For information about our devices and the latest version of this manual please visit www.barix.com

Barix AG Seefeldstrasse 303 8008 Zürich SWITZERLAND

T +41 43 433 22 11 F +41 44 274 28 49

www.barix.com sales@barix.com