

# **RELEASE NOTE**

### STL V03.06

Firmware name:	STL V03.06		
Released:	29. Jan. 2014		
Package name:	abcl_stl_v0306_20140129		
Version overview:	Type Firmware WEB UI FW Ext. 1 FW Ext. 2 FW Ext. 3 Bootloader	File name abclw.rom abclapp.cob sg.bin fs.bin bclio.bin exfull.rom	Version Date VA1.14_20131015 V01.09_20130306 V10.01_20131008 V02.06_20110322 V01.24_20130226 V99.26_20120223

### 1 Hardware Compatibility

This firmware is intended to run on the following devices:

- Exstreamer 100, 105, 110, 200, 205, 500, 1000, P5
- Annuncicom 60, 100, 155, 200, 1000, VME, PS1
- Instreamer 100
- IPAM 100, 102, 200, 300, 302

Note: The firmware may run on other Barix audio devices, however the functionality is not guaranteed.

### 2 New Features and Improvements

Compared to STL v.3.03:

- Added feature #61.59, add QoS parameter in WEB UI network settings.
- Added feature #61.58, add CBR option for MP3 encoding.
- Added feature #61.62, add Bit Reservoir option for MP3 encoding.

### 3 Bugs Fixed In This Version

Compared to STL v.3.03:

- Fixed bug #61.52, changed appearance, to be conform to standard Barix look-and-feel.
- Fixed local loopback not working on encoding-only configurations.

Various corrections have been made to the audio module (song). This is a selection relevant for the IPAM102 based devices:

- Fixed error in initialization, which resulted in a potential data loss while decoding.
- Fixed error in AD mixing which could have caused reduced volume at the receiver.
- #053.80. Fixed audio dropouts in G711 24kHz.
- #053.88. Average buffer level on output now calculated over about 5 seconds rather than the 1-2 seconds in the previous version.

#### 4 Other remarks and known issues

- Volume fading effect works only for connection start.
- Using the SPDIF inputs on Instreamer 100, and streaming a PCM, uLaw or aLaw stream, the optical channel is mandatory.
- Using the AES/EBU or SPDIF inputs, and streaming a PCM, uLaw or aLaw stream, the input signal sample rate and the WEB UI selected sample rate must match.
- Remote relay states on the WEB UI index page, related to remote devices that have not any digital inputs, can be inconsistent.
- Using a full-duplex configuration, and 48Khz PCM stereo as audio format, some audio holes can be audible reloading the WEB UI "configuration" and "application status" pages of the decoding side.
- Using a full-duplex configuration, 16Khz or 48Khz PCM stereo, on devices with hardware modules rev.2 only (IPAM102), in some particular circumstances a muted audio output is possible. Rebooting the device should solve the issue.

# 5 Release generating details<sup>1</sup>

#### 5.1 CVS release tag

abcl\_stl306\_ref301

### 5.2 Compile commands:

make ab\_stl

<sup>1</sup> This information is intended for BARIX developers only

## 6 Legal Information

© 2014 Barix AG, Zurich, Switzerland.

All rights reserved.

All information is subject to change without notice.

All mentioned trademarks belong to their respective owners and are used for reference only.

Barix and STL are trademarks of Barix AG, Switzerland and are registered in certain countries.

For information about our devices and the latest version of this manual please visit <a href="www.barix.com">www.barix.com</a>.

Barix AG Seefeldstrasse 303 8008 Zürich SWITZERLAND

T +41 43 433 22 11 F +41 44 274 28 49

www.barix.com sales@barix.com support@barix.com