Release Notes

Store&Play application v1.65

Firmware Name	Store&Play application v1.65
Release Date	12th June 2017
Package Name	system_update-v1.65.pkg
Version Overview	Component Description Version Date S&P Application Main application v1.65_20170612

1. Hardware Compatibility

This firmware is intended to run on the following BARIX hardware:

- "*Exstreamer Store&Play*" IPAM 390 based Exstreamer 100L

2. Bugs fixed in this version

Compared to the previous version of Store&Play (v1.63):

- STRPLY-519 Fixed an issue that in certain situations it would cause the stream to fade-out unexpectedly and eventually could restart the device
- STRPLY-521 Fixed the issue in which an HTTP stream would not respect its Stop Time as defined in the Playlist
- STRPLY-523 Fixed an issue that in low-buffer situations would cause the application to loop in player state instead of moving to buffering state
- STRPLY-525 Fixed an issue that prevented the Audio Buffer Size to be applied according to the settings
- STRPLY-526 Fixed an issue to prevent setting 0 Volume unexpectedly
- STRPLY-529 Fixed an issue that would cause the device to get stuck in connecting state
- STRPLY-570 Fixed an issue recovering from failover playlist to streaming playback applying Audio Buffer Size accordingly

3. Other remarks and known issues

These known issues will be resolved in future versions:

- STRPLY-504 Fading-out streams nicely
    - Fading-out on connection loss and on pressing Play Next / Play Previous is shorter than 1s. Depending on the URL, fade-out can be overridden by the background playlist and fade-out will be then missing.
- STRPLY-492 and STRPLY-511 Web UI slow response

4. Legal Information

© 2017 Barix AG, Dübendorf, Switzerland.

Barix AG
Ringstrasse 15a
8600 Dübendorf
SWITZERLAND

T +41 43 433 22 11
F +41 44 274 28 49

www.barix.com
sales@barix.com
support@barix.com