Using the IPAM 400

How to do serial

Using an USB to 4 pin serial cable with the speed of 115200 you can connect to your device.

Pin J7	Description
1	TX (White)
2	RX (Green)
3	Ground (black)