



Release Note

ABCL V0.38

Firmware name:	ABCL V0.38		
Released:	02. Sep. 2011		
Package name:	abcl_kit_v0038_20110902.zip		
Version overview:	Type	File name	Version Date
	Firmware	abclw.rom	V00.38_20110902
	WEB UI	abclapp.cob	V01.15_20100902
	FW Ext. 1	sg.bin	V08.22_20110720
	FW Ext. 2	fs.bin	V02.06_20110322
	FW Ext. 3	bclio.bin	V01.19_20110606
	ES Module	esnd.rom	V00.05_20091230
	Bootloader	unifull.spb	V99.22_20110124

© 2011 Barix AG, all rights reserved. All information is subject to change without notice. All mentioned trademarks belong to their respective owners and are used for reference only.



I Hardware Compatibility

This firmware is intended to run on the following devices:

- Exstreamer 100, 105, 110, 120, 200, 205, 500, 1000, P5
- Annunicom 100, 155, 200, 1000
- Instreamer 100
- IPAM 100, 200, 300

2 New Features

The following new features have been implemented in the ABCL v0.38 (compared to version 0.37):

- #053.43, #053.45, #065.15: Exstreamer 205 support
- Technical documentation and BCL Programmers Manual updated

3 Bugs Fixed In This Version

The following bugs have been fixed in the ABCL v0.38 (compared to version 0.37):

- #047.40: use util.js to check network settings
- #091.31: bugfix in “printf” formatting of time with week-day

4 Known Limitations

None.

5 Major Modifications

5.1 Ethersound (#047.39)

The “Ethersound” tab was removed from the WEB UI menu.

In order to switch into Ethersound firmware, open the WEB page “es_confirm.html” on the device (e.g. http://192.168.2.104/es_confirm.html) and follow the instructions.

6 References

	Document
[1]	BCL Programmers Manual 1.15
[2]	ABCL Technical Documentation

7 Legal Information

© 2011 Barix AG, Zurich, Switzerland.

All rights reserved.

All information is subject to change without notice.

All mentioned trademarks belong to their respective owners and are used for reference only.

Barix and ABCL are trademarks of Barix AG, Switzerland and are registered in certain countries.

For information about our devices and the latest version of this manual please visit www.barix.com.

Barix AG
Seefeldstrasse 303
8008 Zürich
SWITZERLAND

T +41 43 433 22 11
F +41 44 274 28 49

www.barix.com
sales@barix.com
support@barix.com

